

# Technical Bulletin

**Model**  
All

**Group**  
7

**Subject:** Reconditioning Leather Upholstery

**Part Identifier**  
72 . .

**Number**  
9002

**ATTENTION: Service Manager/Service Technician**

**Concern:**

1. Replacing leather seat covers and upholstery rather than repairing.
2. Reconditioning leather seat covers and upholstery due to:
  - a. accident damage
  - b. normal wear

**Service Information:**

Porsche Cars North America, Inc. recommends **COLOR-PLUS** products for repair to leather seat covers and upholstery (door panels, consoles, steering wheels, etc.).

Their products provide for minor repairs and complete re-dyeing "in-house" with a minimum of disassembly, allowing a substantial reduction in time and expense. Front seats can be dyed without removing seat covers.

Standard Porsche leather colors from M.Y. 1987 (except pearl and 1988 911 jubilee silver blue) will be matched and assigned a formula number for your convenience.

A **Color-Plus** brochure is enclosed, including a list of products, prices and tips on leather care and repair. For additional information on reconditioning leather, call Color-Plus at (201) 659-4708 or write to:

Color-Plus  
P.O. Box 404  
Kearny, NJ 07032

PORSCHE CARS NORTH AMERICA INC.

Dealership	Service manager _____	Shop foreman _____	Service technician _____	_____	_____	_____
Distribution	Asst. manager _____	Warranty admin. _____	Service technician _____	_____	_____	_____
Routing						

©1990 Porsche Cars North America, Inc. All Rights Reserved Porsche Technical Publications



# SERVICE

Page 1 of 1  
June 22, 1990