

Technical Bulletin

Model
911 C2/C4

Group
5

Subject: Central Locking and Rear Spoiler
Control Unit Location

Part Identifier
5782/6674

Number
9004

ATTENTION: Service Manager/Service Technician

Models Affected: *911 Carrera 2/4, model year '91 (M)*

Concern: The location for the central locking control unit and the rear spoiler control unit changed with '91 (M) model year.

Service Information: The wiring plugs for the rear spoiler control unit and the model year '89 (K) and '90 (L) central locking control unit are similar. The control units **must not** be interchanged. The electric circuitry is different. Installation of the wrong control unit damages the control unit and wiring.

Location of Control Units

Model year '89 (K) and '90 (L)

Rear spoiler control unit - under right seat

Central locking control unit - under dashboard right side

Model year '91 (M)

Rear spoiler control unit - under dashboard right side

Central locking/alarm control unit - under right seat

Parts Information:

Rear spoiler control unit: Part Number 911 618 112 00

Central locking control unit
up to end of '90 (K and L): Part Number 911 618 113 01

Central locking/alarm control unit
from '91 (M): Part Number 928 618 260 00

PORSCHÉ CARS NORTH AMERICA, INC.

Dealership	Service manager _____	Shop foreman _____	Service technician _____	_____	_____
Distribution	Asst. manager _____	Warranty admin. _____	Service technician _____	_____	_____
Routing					

© 1990 Porsche Cars
North America, Inc.
All rights reserved. Cannot be
reproduced without written permission.
Porsche Technical Publications



SERVICE

Page 1 of 1
December 14, 1990